Department of Cultural Affairs Division of Museums & History

EAST ELY RAILROAD DEPOT MUSEUM SITE

1100 Avenue A Ely, Nevada 89301

Site Number: 9857 STATE OF NEVADA PUBLIC WORKS DIVISION FACILITY CONDITION ANALYSIS



Report distributed in October 2021

Department of Cultural Affairs Division of Museums & History

The Facility Condition Analysis Program was created under the authority found in NRS 341.128. The State Public Works Division develops this report using cost estimates based on contractor pricing which includes materials, labor, location factors and profit and overhead. The costs of project design, management, special testing and inspections, inflation and permitting fees are not included. Cost estimates are derived from the R.S. Means Cost Estimating Guide and from comparable construction costs of projects completed by SPWD project managers.

The deficiencies outlined in this report were noted from a visual survey. This report does not address routine maintenance needs. Recommended projects do not include telecommunications, furniture, window treatments, space change, program issues, or costs that could not be identified or determined from the survey and available building information. If there are buildings without projects listed, this indicates that only routine maintenance needs were found. This report considers probable facility needs for a 10 year planning cycle.

This report is not a guarantee of funding and should not be used for budgeting purposes. This report is a planning level document for agencies and State Public Works Division to assess the needs of the Building and/or Site and to help support future requests for ADA upgrades / renovations, Capital Improvement Projects, and maintenance. The final scope and estimate of any budget request should be developed by a qualified individual. Actual project costs will vary from those proposed in this report when the final scope and budget are developed.

Establishing a Facility Condition Needs Index (FCNI) for each building

The FCA reports identify maintenance items and establish construction cost estimates. These costs are summarized at the end of the report and noted as construction costs per square foot. A FCNI is commonly used by facility managers to make a judgment whether to recommend whole replacement of facilities, rather than expending resources on major repairs and improvements. The FCNI is a ratio between the proposed facility upgrade costs and facility replacement costs (FRC). Those buildings with indices greater than .50 or 50% are recommended to be considered for complete replacement.

Class Definitions

PRIORITY CLASS 1 - Currently Critical (Immediate to Two Years)

Projects in this category require immediate action to return a facility to normal operation, stop accelerated deterioration, correct a fire/life safety hazard, or correct an ADA requirement.

PRIORITY CLASS 2 - Necessary - Not Yet Critical (Two to Four Years)

Projects in this category include conditions requiring appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further.

PRIORITY CLASS 3 - (Four to Ten Years)

Projects in this category include items that represent a sensible improvement to existing conditions. These items are not required for the most basic function of a facility; however, Priority 3 projects will either improve overall usability and/or reduce long-term maintenance.

Site num	ber: 9857	Facility Condition Neo	eds Index I	Report		Cost to	Cost to	Cost to	Total Cost	Cost to	
Index #	Building Name		Sq. Feet	Yr. Built	Survey Date	Repair: P1	Repair: P2	Repair: P3	to Repair	Replace	FCNI
2128	EAST ELY RAILROAD	FREIGHT BARN	12865	1906	11/7/2017	\$250,200	\$357,000	\$64,325	\$671,525	\$2,573,000	26%
	1100 Avenue A	Ely									
2227	EAST ELY RAILROAD	DEPOT	8600	1907	11/7/2017	\$111,300	\$504,400	\$43,000	\$658,700	\$2,795,000	24%
	1100 Avenue A	Ely									
9857	EAST ELY RAILROAD	DEPOT MUSEUM SITE		1906	11/7/2017	\$4,400	\$0	\$0	\$4,400		0%
	1100 Avenue A	Ely									
		Report Totals	21,465			\$365,900	\$861,400	\$107,325	\$1,334,625	\$5,368,000	25%

Acronym	Definition
Building Codes, Laws, Regulations and Guidelines	
AHJ	Authority Having Jurisdiction
AWWA	American Water Works Association
HVAC	Heating, Ventilating & Air Conditioning
IBC	International Building Code
ICC	International Code Council
IEBC	International Existing Building Code
IECC	International Energy Conservation Code
IFC	International Fire Code
IFGC	International Fuel Gas Code
IRC	International Residential Code
NFPA	National Fire Protection Association
NEC	National Electrical Code
OSHA	Occupational Safety and Health Administration
SAD	Standards for Accessible Design
SMACNA	Sheet Metal and Air Conditioning Contractors
	National Association
UMC	Uniform Mechanical Code
UPC	Uniform Plumbing Code
State of Nevada	
CIP	Capital Improvement Project
FCA	Facility Condition Analysis
FCNI	Facility Condition Needs Index
FRC	Facility Replacement Cost
NAC	Nevada Administrative Code
NDEP	Nevada Department of Environmental Protection
NRS	Nevada Revised Statutes
SFM	State Fire Marshal
SHPO	State Historic Preservation Office
SPWD	State Public Works Division
Miscellaneous	
DDC	Direct Digital Controls
FRP	Fiberglass Reinforced Plastic
GFCI	Ground Fault Circuit Interrupter
LED	Light Emitting Diode
PRV	Pressure Regulating Valve
TDD	Telecommunications Device for the Deaf
VCT	Vinyl Composite Tile

Acronyms List

This is a generic acronym list of commonly used terms throughout the Facility Condition Analysis report.

Table of Contents

Building Name	Index #
EAST ELY RAILROAD DEPOT MUSEUM SITE	9857
EAST ELY RAILROAD DEPOT	2227
EAST ELY RAILROAD FREIGHT BARN	2128

EAST ELY RAILROAD DEPOT MUSEUM SITE

BUILDING REPORT

The East Ely Railroad Museum site is located on the Nevada Northern Railway Historical site and consists of two structures owned by the State of Nevada including the land ten feet out from the foundation. The buildings are served by city water and sewer services and electric power is provided by Mt. Wheeler Power. There is parking including ADA accessible parking which is technically not maintained by the State of Nevada and concrete sidewalks around the depot which are in good shape. The Freight Barn is located west of the Depot and does not have an ADA accessible route from parking to the barn, but there is a new ADA accessible ramp from the dirt parking area to the barn's exterior walkway.

PRIORITY CLASS 1 PROJECTSTotal Construction Cost for Priority 1 Projects:\$4,400Currently CriticalImmediate to Two Years

ADA SIGNAGE & STRIPING

The ADA provides for accessibility to sites and services for people with physical limitations. The concrete parking area and passenger loading area are missing proper signage and striping to comply with ADA requirements. This project would provide for striping, signage and any other necessary upgrades to the parking space. The 2018 IBC, ICC/ANSI A117.1, NRS 338.180 and the most current version of the ADA Standards for Accessible Design were used as a reference for this project.

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

Priority Class 1:	\$4,400
Priority Class 2:	\$0
Priority Class 3:	\$0
Grand Total:	\$4,400

Project Index #: 9857ADA1 Construction Cost \$4,400

Total Construction Cost for F

State of Nevada / Tourism & Cultural AffairsEAST ELY RAILROAD DEPOTSPWD Facility Condition Analysis - 2227Survey Date:11/7/2017

EAST ELY RAILROAD DEPOT BUILDING REPORT

The Ely Railroad Depot is located at the railhead of the former Kennecott Mine railway. When the mine closed in the early 1980s, the site was transferred to a local non-profit agency. In turn, the depot and freight barn were brought under the auspices of the State of Nevada, and have operated as a museum and display since 1992. The site was designated a National Historical District in 1993.

The depot was constructed in 1907 and is presently used for offices, display and storage. The building is a two level wood and stone framed building with a composition roofing system at the main roof and a metal roof at the north facing shed roof. There is a partial basement used primarily for storage. It has electric baseboard heaters, a new fire alarm system and the lower level museum store is mostly ADA compliant. The upper level offices and displays are not accessible as the only access is a stairway.

PRIORITY CLASS 1 PROJECTS	8	Total Construction Cost for Priority 1 Projects:	\$111,300
Currently Critical	Immediate to Tw	vo Years	

ADA AUDIO/ VISUAL PRESENTATION

The Railroad Depot is open to the public for tours and train rides. The second floor is home to most of the historical Depot artifacts and where a large portion of the tour takes place. There is no ADA access to this area. This project would provide for an ADA accessible location inside the lower level of the building for an audio / visual (A/V) presentation of the inaccessible portions of the Depot and site. This project includes funds for an audio / visual consultant to outline and document the exhibits and purchase and installation of all required A/V equipment including signage, TDD equipment and minor remodeling of the public area of the building as required to accommodate this program. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate. The 2018 IBC, ICC/ANSI A117.1, NRS 338.180 and the most current version of the Americans with Disabilities Act Accessible Guidelines (ADAAG) was used as a reference for this project. This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

ADA RESTROOM UPGRADE

The building does not have an accessible restroom. The existing restroom does not meet the ADA requirements. A complete retrofit is necessary. This project would provide funding for remodeling the men's and women's restrooms per ADA regulations. Items may include a new sink, toilet, hardware, mirrors, fixtures, flooring and paint. The 2018 IBC, ICC/ANSI A117.1, NRS 338.180 and the most current version of the ADA Standards for Accessible Design were used as a reference for this project.

SHED ROOF REPLACEMENT

The metal roof on the north elevation of the building was in poor condition at the time of the survey and had active leaks. This shed roof partially covers the boarding platform and has a gutter and downspout system that is in poor condition. When the gutters leak, water pools up and freezes on the boarding platform creating a safety hazard. The gutters and downspouts around the rest of the building are also in poor condition with active leaks. It is recommended to re-roof the metal shed roof and repair or replace the gutters and downspouts around the entire building. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 06/03/2002 and 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

Project Index #: 2227ADA2 Construction Cost \$49,700

Project Index #:

Construction Cost

2227ADA1

2227EXT4

\$30,800

\$30,800

Project Index #:

Construction Cost

PRIORITY CLASS 2 PROJECTS

Necessary - Not Yet Critical Two to Four Years

EXTERIOR FINISHES

The exterior finishes are in poor condition. It is important to maintain the finish, weather resistance and appearance of the building. This project would provide funding to protect the exterior of the building excluding the roof. Included in the cost is sanding, priming and painting the wood trim and soffits, power washing and painting the stucco, cleaning and sealing the stone masonry and caulking of the windows, flashing, fixtures and all other penetrations. It is recommended that the building be painted, sealed and caulked in the next 3 - 4 years and that this project be scheduled on a cyclical basis to maintain the integrity of the structure. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

HVAC SYSTEM UPGRADE

The existing HVAC system consists of electric baseboard heaters and several window mounted air conditioners. The electric heaters are inefficient and the air conditioners only cover small areas of the building. There is a need for cooling equipment throughout the building to provide a comfortable interior environment in the summer. This project would provide for replacing the existing equipment with a central HVAC system including exterior ground mounted propane fired packaged units that provide heating as well as air conditioning and installing duct work and controls. Propane gas service will be required and is included in the cost. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 06/03/2002 and 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

LIGHTING UPGRADE

The existing lighting fixtures are the older fluorescent type, and are not energy efficient. This project will upgrade fixtures to higher efficiency units with a longer life cycle. 5,000K LED lamps, without the ballasts, are suggested, and new tombstones (if needed). Occupancy sensors will be installed in low occupancy areas for additional savings. Electrical wiring upgrades are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

STRUCTURAL REPAIRS

Due to the age of the building and the structural codes at the time, the structural system may be deficient and should be evaluated and repaired. Some shoring work has been done in the basement by applying gunite to the foundation walls, but no other major structural upgrades have taken place since the State acquired the building in 1992. The estimate is a general figure representing a likely scenario of installing blocking, steel structural ties, cables. etc... to increase the lateral and vertical load resistance. An evaluation and design must be conducted by a licensed structural engineer, of which the costs are not included in this estimate. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 06/03/2002 and 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

Project Index #: 2227EXT5

Construction Cost \$43,000

Project Index #: 2227HVA1 **Construction Cost** \$172,000

2227ENR1

2227STR1

\$25,800

Project Index #:

Project Index #:

Construction Cost \$154,000

Construction Cost

Total Construction Cost for Priority 2 Projects: \$504,400

WINDOW REPLACEMENT

The windows are original, single pane construction in a wooden frame. These older windows are drafty, not energy efficient and the wooden frames have deteriorated significantly. This project recommends replacing the windows with dual pane, higher efficiency units. This estimate is for the replacement of 44 units including wooden frames and includes additional costs for the unique historical nature of the building. Removal and disposal of the existing windows is included in this estimate. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements for this building.

This project or a portion thereof was previously recommended in the FCA report dated 06/03/2002 and 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

PRIORITY CLASS 3 PROJECTS

Long-Term Needs

INTERIOR FINISHES

Total Construction Cost for Priority 3 Projects:

Construction Cost \$43,000

Project Index #:

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next 4 - 5 years and that this project be scheduled on a cyclical basis to maintain the integrity of the structure. Prior to painting, all surfaces should be repaired and prepped. Additional abatement costs would be required if lead is detected in the original paint. An epoxy-based paint should be utilized in wet areas for durability. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

BUILDING INFORMATION:

Gross Area (square feet):	8,600		IBC Occupancy Type 1:	100 % B
Year Constructed:	1907		IBC Occupancy Type 2:	%
Exterior Finish 1:	60 %	Painted Stucco / EIFS	Construction Type:	Stone Masonry & Wood
Exterior Finish 2:	40 %	Stone Masonry	IBC Construction Type:	V-B
Number of Levels (Floors):	2	Basement? Yes	Percent Fire Supressed:	0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

Priority Class 1:	\$111,300	Project Construction Cost per Square Foot:	\$76.59
Priority Class 2:	\$504,400	Total Facility Replacement Construction Cost:	\$2,795,000
Priority Class 3:	\$43,000	Facility Replacement Cost per Square Foot:	\$325
Grand Total:	\$658,700	FCNI:	24%

Project Index #: 2227EXT3 Construction Cost \$109.600

\$43,000

2227INT1

Four to Ten Years

State of Nevada / Tourism & Cultural AffairsEAST ELY RAILROAD FREIGHT BARNSPWD Facility Condition Analysis - 2128Survey Date:11/7/2017

EAST ELY RAILROAD FREIGHT BARN BUILDING REPORT

The Freight Barn is located at the railhead of the former Kennecott Mine railway. When the mine closed in the early 1980s, the site was transferred to a local non-profit agency. In turn, the freight barn and nearby railroad depot were brought under the auspices of the State of Nevada, and have operated as a museum and display since 1992. The site was designated a National Historical District in 1993.

The freight barn was constructed in 1906 and is presently used for storage and as the maintenance shop. There are plans for public display areas and a portion of the structure is open to the public. It is a wood framed structure with a stone and concrete foundation and a metal roofing system. The facility has undergone a remodel including ADA access, Men's and Women's restrooms, some wood plank flooring replacement and rehabilitation, structural stabilization, a new fire alarm and detection system and new exterior painted metal siding. The restrooms have a small electric heating unit, but the rest of the building does not have an HVAC system nor fire sprinklers.

PRIORITY CLASS 1 PROJECTS	Total Construction Cost for Priority 1 Projects:	\$250,200
Currently Critical	Immediate to Two Years	

ADA SIGNAGE

Project Index #:2128ADA1Construction Cost\$1,800

2128ADA2

2128SFT3

\$4.000

Project Index #:

Construction Cost

Project Index #:

Construction Cost \$244,400

Americans with Disabilities Act (ADA) regulations pertaining to building access has established building signage criteria for permanent spaces in buildings. The criteria includes: sign mounting heights and locations; character heights and proportions; raised and Braille characters/pictograms; and sign contrast and finish. The signage in this facility does not comply with this criteria. It is recommended that applicable signage be installed where required and that the restroom ADA signs be moved to a compliant location. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate. NRS 338.180, IBC - 2018, ICC/ANSI A117.1 and the most current version of the Americans with Disabilities Act Accessible Guidelines (ADAAG) were used as a reference for this project.

This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

DUAL LEVEL DRINKING FOUNTAIN INSTALLATION

This building does not contain a drinking fountain. It is recommended to install a drinking fountain for the comfort of the occupants. The 2018 IBC Section 1109.5 states where a water fountain is provided, at least half should be accessible. This project would provide funding for the purchase and installation of an accessible fixed high/ low ADA drinking fountain.

This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

FIRE SUPPRESSION SYSTEM INSTALLATION

This building houses irreplaceable records for the site dating back to the early 1900s. The square footage of the building exceeds 12,000 square feet and does not have an automatic fire suppression system. Pursuant to the Nevada State Fire Marshal Regulation, NAC 477.915 (c) states, that every building owned or occupied by the state which is designated as a B occupancy, or has a floor area greater than 12,000 square feet on any floor or 24,000 square feet on all floors or is an R-1 or R-2 occupancy, must have sprinklers installed when the building is remodeled or an addition is proposed. This project would provide funding for the installation of a freeze protected fire sprinkler system and backflow prevention in the event the building is remodeled or an addition is undertaken. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate. This project or a portion thereof was previously recommended in the FCA report dated 06/03/2002. It has been amended accordingly to reflect conditions observed during the most recent survey date of 08/25/2011.

30-Sep-21

PRIORITY CLASS 2 PROJECTS

Necessary - Not Yet Critical Two to Four Years

DUST COLLECTION SYSTEM INSTALLATION

The existing wood working equipment has no dust collection capacity. In order to reduce the possibility of damage or injury, each piece of equipment should have full collection capability. This project will provide for the installation of a full dust collection system to minimize explosion hazard and disruption to production.

EXTERIOR DECK REPAIRS

The building has a boardwalk on the street side of the building and a loading dock on the track side. They were recently refurbished with new wood planks that were nailed to the framing. The nails are proving to be insufficient and should be replaced with screws. As the wood ages, it pushes the nails out and causes a safety hazard. This project provides for removing the nails and replacing them with deck screws along the entire boardwalk and loading dock.

This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

FLOORING REPLACEMENT - FREIGHT OFFICE

The "Battleship" linoleum flooring in the Freight Office is damaged and reaching the end of its useful life. It is recommended that the flooring be replaced. This project would provide for removal and disposal of the existing flooring and installation of new "Battleship" linoleum. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 06/03/2002 and 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

HVAC SYSTEM INSTALLATION

This building is equipped with a wood burning stove in the freight office and two wall mounted electric heaters in the restrooms and does not have any cooling equipment. The rest of the building is not conditioned space. Future plans for the building include interactive displays, a community center, and special events which would all benefit from adding heating and cooling for the entire building. This project would provide for replacing the existing heaters with roof mounted propane fired packaged units that provide heating as well as air conditioning to the entire building. Propane gas service will be required and is included in the cost. This project should be implemented after or concurrent with the Insulate Building project and coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 06/03/2002 and 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

INSULATE BUILDING

This building has no insulation. The temperature extremes are contributing to accelerated decay of the contents, which include historical artifacts awaiting restoration and/or on display. This project will install batt insulation in the walls and ceilings to help moderate temperature fluctuations. It may be possible to use a foamed-in system to fill the cavities where applicable; costs are similar to the batt insulation provided for in this project. This project should be implemented before or concurrent with the HVAC System Installation project and coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements which are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

Project Index #: 2128ENR1 **Construction Cost** \$113.000

Construction Cost \$9,200

2128EXT4

2128HVA1

Project Index #:

Project Index #: 2128ENV1 **Construction Cost** \$24,900

Total Construction Cost for Priority 2 Projects: \$357,000

Project Index #: 2128INT2

Construction Cost \$14,400

Project Index #:

INTERIOR FINISHES

The interior finishes are in poor condition. The interior finishes are in fair condition. Most of the walls and ceilings are unfinished wood, but there are painted walls and ceilings in the restrooms and the shop areas. It is recommended that the finished interior walls and ceilings be painted at least once in the next 3 - 4 years and that this project be scheduled on a cyclical basis to maintain the integrity of the structure. Prior to painting, all surfaces should be repaired and prepped. Additional abatement costs would be required if lead is detected in the original paint. An epoxy-based paint should be utilized in wet areas for durability.

LIGHTING UPGRADE

The existing lighting fixtures are the older fluorescent type, and are not energy efficient. This project will upgrade fixtures to higher efficiency units with a longer life cycle. 5,000K LED lamps, without the ballasts, are suggested, and new tombstones (if needed). Occupancy sensors will be installed in low occupancy areas for additional savings. Electrical wiring upgrades are not included in this estimate.

This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

PEST CONTROL

There are numerous pigeon and rodent droppings throughout this building. Due to the potential risk of disease, this project provides for treatment and clean up of the pigeon and rodent droppings by a licensed pest control business.

WINDOW REPLACEMENT

The windows are original, single pane construction in a wooden frame. These older windows are drafty, not energy efficient and the wooden frames have deteriorated significantly. This project recommends replacing the windows with dual pane, higher efficiency units. This estimate is for the replacement of 6 units including wooden frames and includes additional costs for the unique historical nature of the building. Removal and disposal of the existing windows is included in this estimate. This project should be coordinated with the Nevada State Historical Preservation Office for possible restrictions or requirements for this building.

This project or a portion thereof was previously recommended in the FCA report dated 08/25/2011. It has been amended accordingly to reflect conditions observed during the most recent survey date of 11/07/2017.

Four to Ten Years

Total Construction Cost for Priority 3 Projects:

PRIORITY CLASS 3 PROJECTS

Long-Term Needs

EXTERIOR FINISHES

The exterior finishes are in fair condition. It is important to maintain the finish, weather resistance and appearance of the building. This project would provide funding to protect the exterior of the building excluding the roof. Included in the cost is painting the metal panels and wood and caulking of the windows, flashing, fixtures and all other penetrations. It is recommended that the building be painted in the next 4 - 5 years and that this project be scheduled on a cyclical basis to maintain the integrity of the structure.

Project Index #: 2128INT3 **Construction Cost** \$12,000

Project Index #:

Construction Cost

2128ENR2

\$38,600

\$64,325

\$64.325

2128EXT2

Project Index #: 2128ENV2 **Construction Cost** \$1,300

2128EXT3 **Project Index #: Construction Cost** \$14,900

Project Index #:

Construction Cost

BUILDING INFORMATION:

Gross Area (square feet): 12,865	IBC Occupancy Type 1:	50 % S-2
Year Constructed: 1906	IBC Occupancy Type 2:	50 % A-3
Exterior Finish 1: 90 % Painted Metal Siding	Construction Type:	Wood Framed
Exterior Finish 2: 10 % Painted Wood Siding	IBC Construction Type:	V-B
Number of Levels (Floors): 1 Basement? Yes	Percent Fire Supressed:	0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

Priority Class 1:	\$250,200	Project Construction Cost per Square Foot:	\$52.20
Priority Class 2:	\$357,000	Total Facility Replacement Construction Cost:	\$2,573,000
Priority Class 3:	\$64,325	Facility Replacement Cost per Square Foot:	\$200
Grand Total:	\$671,525	FCNI:	26%

NOTES:

The deficiencies outlined in this report were noted from a visual survey. The costs do not represent the cost of a complete facility renovation or maintenance needs. Recommended projects do not include telecommunications, furniture, window treatment, space change, program issues, relocation, swing space, or costs that could not be identified or determined from the survey and available building information.

Individual projects and costs noted herein may be impacted by new construction materials or methods, agency projects, and pending or proposed Capital Improvement Projects (CIP).

This report was created under the authority found in NRS 341.128 by the State Public Works Division and should be utilized as a planning level document.

REPORT DEVELOPMENT:

State Public Works Division	515 E. Musser Street, Suite 102	(775) 684-4141 voice
Facilities Condition Analysis	Carson City, Nevada 89701-4263	(775) 684-4142 facsimile



East Ely Railroad Depot Museum Site - Site #9857 Description: ADA Parking Signage & Striping Needed.



East Ely Railroad Depot - Building #2227 Description: Exterior Finishes on North Elevation.



East Ely Railroad Depot - Building #2227 Description: ADA Restroom Upgrade.



East Ely Railroad Depot - Building #2227 Description: Upper Level Interior Hallway.



East Ely Railroad Depot - Building #2227 Description: Lower Level Interior.



East Ely Railroad Depot - Building #2227 Description: Lower Level Interior.



East Ely Railroad Freight Barn - Building #2128 Description: Exterior of the Building.



East Ely Railroad Freight Barn - Building #2128 Description: Accessible Ramp to Building Added.



East Ely Railroad Freight Barn - Building #2128 Description: Dust Collection System Installation Needed.



East Ely Railroad Freight Barn - Building #2128 Description: Interior of the Building.