State of Nevada

Department of Conservation and Natural Resources
Division of State Parks
Wild Horse State Recreation Area
Facility Condition Analysis

WILD HORSE STATE RECREATION AREA

HC 31 Box 265 Elko, Nevada 89801

Site Number: 9935 STATE OF NEVADA PUBLIC WORKS DIVISION FACILITY CONDITION ANALYSIS



Report Printed in June 2015

State of Nevada Department of Conservation and Natural Resources Division of State Parks Wild Horse State Recreation Area Facility Condition Analysis

The Facility Condition Analysis Program was created under the authority found in NRS 341.128. The State Public Works Division develops this report using cost estimates based on contractor pricing which includes materials, labor, location factors and profit and overhead. The costs of project design, management, special testing and inspections, inflation and permitting fees are not included. Cost estimates are derived from the R.S. Means Cost Estimating Guide and from comparable construction costs of projects completed by SPWD project managers.

The deficiencies outlined in this report were noted from a visual survey. This report does not address routine maintenance needs. Recommended projects do not include telecommunications, furniture, window treatments, space change, program issues, or costs that could not be identified or determined from the survey and available building information. If there are buildings without projects listed, this indicates that only routine maintenance needs were found. This report considers probable facility needs for a 10 year planning cycle.

This report is not a guarantee of funding and should not be used for budgeting purposes. This report is a planning level document for agencies and State Public Works Division to assess the needs of the Building and/or Site and to help support future requests for ADA upgrades / renovations, Capital Improvement Projects and maintenance. The final scope and estimate of any budget request should be developed by a qualified individual. Actual project costs will vary from those proposed in this report when the final scope and budget are developed.

Establishing a Facility Condition Needs Index (FCNI) for each building

The FCA reports identify maintenance items and establish construction cost estimates. These costs are summarized at the end of the report and noted as construction costs per square foot. A FCNI is commonly used by facility managers to make a judgment whether to recommend whole replacement of facilities, rather than expending resources on major repairs and improvements. The FCNI is a ratio between the proposed facility upgrade costs and facility replacement costs (FRC). Those buildings with indices greater than .50 or 50% are recommended to be considered for complete replacement.

Class Definitions

PRIORITY CLASS 1 - Currently Critical (Immediate to Two Years)

Projects in this category require immediate action to return a facility to normal operation, stop accelerated deterioration, correct a fire/life safety hazard, or correct an ADA requirement.

PRIORITY CLASS 2 - Necessary - Not Yet Critical (Two to Four Years)

Projects in this category include conditions requiring appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further.

PRIORITY CLASS 3 - (Four to Ten Years)

Projects in this category include items that represent a sensible improvement to existing conditions. These items are not required for the most basic function of a facility; however, Priority 3 projects will either improve overall usability and/or reduce long-term maintenance.

Site num	ber: 9935	Facility Condition Need	ds Index l	Report		Cost to	Cost to	Cost to	Total Cost	Cost to	
Index #	Building Name		Sq. Feet	Yr. Buil	Survey Date		Repair: P2	Repair: P3	to Repair	Replace	FCNI
1315	PARK OFFICE / SHOP		3400	1982	7/23/2014	\$25,500	\$120,600	\$0	\$146,100	\$765,000	19%
	HC 31, Box 26	Wild Horse SRA									
1316	RESTROOM #3		400	1982	7/23/2014	\$5,000	\$8,640	\$0	\$13,640	\$80,000	17%
	HC 31, Box 26	Wild Horse SRA									
2316	RESIDENCE GARAGE #1		672	1990	7/23/2014	\$0	\$6,720	\$0	\$6,720	\$50,400	13%
	HC 31, Box 26	Wild Horse SRA									
1313	RESIDENCE #2		2304	1982	7/23/2014	\$4,000	\$46,440	\$0	\$50,440	\$403,200	13%
	HC 31, Box 26	Wild Horse SRA									
1312	RESIDENCE #1		2304	1982	7/23/2014	\$0	\$44,040	\$0	\$44,040	\$403,200	11%
	HC 31, Box 26	Wild Horse SRA									
1314	RESTROOM #2		507	1982	7/23/2014	\$0	\$5,070	\$0	\$5,070	\$50,700	10%
	HC 31, Box 26	Wild Horse SRA									
1602	RESTROOM #1		200	1980	7/23/2014	\$0	\$1,000	\$1,000	\$2,000	\$20,000	10%
	HC 31, Box 26	Wild Horse SRA									
2317	RESIDENCE GARAGE #2	2	900	2002	7/23/2014	\$0	\$4,500	\$0	\$4,500	\$67,500	7%
	HC 31, Box 26	Wild Horse SRA									
1311	UTILITY SHED		200	1982	7/23/2014	\$0	\$200	\$0	\$200	\$4,000	5%
	HC 31, Box 26	Wild Horse SRA									
9935	WILD HORSE STATE RE	CREATION AREA SITE			7/23/2014	\$47,500	\$0	\$169,150	\$216,650		0%
	HC 31, Box 265	Wild Horse SRA									
2733	RAMADA #2		144	2007	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3276	RAMADA #8		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3280	RAMADA #12		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3279	RAMADA #11		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3278	RAMADA #10		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3277	RAMADA #9		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									

Thursday, June 25, 2015

Site num	ber: 9935	Facility Condition Need	ds Index	Report		Cost to	Cost to	Cost to	Total Cost	Cost to	FCNI
Index #	Building Name		Sq. Feet	Yr. Buil	Survey Date		Repair: P2	Repair: P3	to Repair	Replace	
3275	RAMADA #7		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3274	RAMADA #6		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
2736	RAMADA #5		144	2007	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
2734	RAMADA #3		144	2007	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3283	RAMADA #15		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
2732	RAMADA #1		144	2007	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
2735	RAMADA #4		144	2007	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3293	RAMADA #25		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3303	BOAT INSPECTION STAT	ION	100	2013	7/23/2014	\$0	\$0	\$0		\$4,000	
	HC 31, Box 26	Wild Horse SRA									
3302	RAMADA #34		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3301	RAMADA #33		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3300	RAMADA #32		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3299	RAMADA #31		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3298	RAMADA #30		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3297	RAMADA #29		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3296	RAMADA #28		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3281	RAMADA #13		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									

Thursday, June 25, 2015

Site num	lber: 9935	Facility Condition Nee	ds Index I	Report		Cost to	Cost to	Cost to	Total Cost	Cost to	
Index #	Building Name		Sq. Feet	Yr. Buil	Survey Date		Repair: P2	Repair: P3	to Repair	Replace	FCNI
3294	RAMADA #26		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3282	RAMADA #14		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3292	RAMADA #24		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3291	RAMADA #23		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3290	RAMADA #22		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3289	RAMADA #21		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3288	RAMADA #20		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3287	RAMADA #19		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3286	RAMADA #18		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3285	RAMADA #17		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3284	RAMADA #16		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
3295	RAMADA #27		144	2013	7/23/2014	\$0	\$0	\$0		\$3,600	
	HC 31, Box 26	Wild Horse SRA									
		Report Totals:	15,883	3		\$82,000	\$237,210	\$170,150	\$489,360	\$1,970,400	25%

Thursday, June 25, 2015

Table of Contents

Building Name	Index #	
WILD HORSE STATE RECREATION AREA SITE	9935	
BOAT INSPECTION STATION	3303	No Current Projects
RAMADA #34	3302	No Current Projects
RAMADA #33	3301	No Current Projects
RAMADA #32	3300	No Current Projects
RAMADA #31	3299	No Current Projects
RAMADA #30	3298	No Current Projects
RAMADA #29	3297	No Current Projects
RAMADA #28	3296	No Current Projects
RAMADA #27	3295	No Current Projects
RAMADA #26	3294	No Current Projects
RAMADA #25	3293	No Current Projects
RAMADA #24	3292	No Current Projects
RAMADA #23	3291	No Current Projects
RAMADA #22	3290	No Current Projects
RAMADA #21	3289	No Current Projects
RAMADA #20	3288	No Current Projects
RAMADA #19	3287	No Current Projects
RAMADA #18	3286	No Current Projects
RAMADA #17	3285	No Current Projects
RAMADA #16	3284	No Current Projects
RAMADA #15	3283	No Current Projects
RAMADA #14	3282	No Current Projects
RAMADA #13	3281	No Current Projects
RAMADA #12	3280	No Current Projects
RAMADA #11	3279	No Current Projects
RAMADA #10	3278	No Current Projects
RAMADA #9	3277	No Current Projects
RAMADA #8	3276	No Current Projects
RAMADA #7	3275	No Current Projects
RAMADA #6	3274	No Current Projects
RAMADA #5	2736	No Current Projects
RAMADA #4	2735	No Current Projects

2734	No Current Projects
2733	No Current Projects
2732	No Current Projects
2317	
2316	
1602	
1316	
1315	
1314	
1313	
1312	
1311	
	2733 2732 2317 2316 1602 1316 1315 1314 1313

State of Nevada / Conservation & Natural Resources WILD HORSE STATE RECREATION AREA SITE

SPWB Facility Condition Analysis - 9935

Survey Date: 7/23/2014

WILD HORSE STATE RECREATION AREA SITE **BUILDING REPORT**

The Wild Horse State Recreation Area is located 67 miles north of Elko. The area occupies 120 acres of which 80 of the acres are managed and maintained. Park activities include camping, picnicking, swimming, fishing and boating, and are open year round. There is a 34 unit campground, day use area and a boat ramp along with a Visitor's Center and maintenance shop, garages and two staff residences. The site is served by 600 foot deep well which pumps water to three 10,000 gallon underground storage tanks. During the survey of 2014, staff indicated that one tank is off line and may need to be replaced due to damage. This system supplies water to the campground facilities, Visitor's Center and residences. Propane provides fuel for heating needs.

PRIORITY CLASS 1 PROJECTS

Total Construction Cost for Priority 1 Projects: \$47,500

Currently Critical

Immediate to Two Years

Project Index #: 9935ADA1 SITE ADA ISSUES **Construction Cost** \$10,000

The parking in the Day Use area and the route of travel from the parking space to the accessible picnic table are not fully ADA compliant. It is recommended that the parking area and route of travel be made accessible including updated signage. A concrete ADA parking space is included in this estimate.

The 2012 IBC, ICC/ANSI A117.1 - 2009, NRS 338.180 and the most current version of the ADA Standards For Accessible Design were used as a reference for this project.

This project or a portion thereof was previously recommended in the FCA report dated 08/21/2002 and 11/7/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 7/23/2014

WATER STORAGE TANK REPLACEMENT

9935SIT5 **Project Index #: Construction Cost** \$27,500

Site number: 9935

There is a 10,000 gallon underground water storage tank that is leaking and no longer in use according to staff. This project would provide for the removal of the existing tank and installation of a new 10,000 gallon water storage tank including all required excavation and connections to existing water system.

WELL SYSTEM TELEMETRY REPLACEMENT

Project Index #: 9935SIT6 **Construction Cost** \$10,000

The existing well water telemetry system is no longer operational. Staff has to manually activate well pumps to fill tanks. This is not efficient. This project would provide for a new telemetry system including software to be installed.

PRIORITY CLASS 3 PROJECTS

Total Construction Cost for Priority 3 Projects: \$169,150

Long-Term Needs

Four to Ten Years

AC PAVING INSTALLATION

Project Index #: 9935SIT2 **Construction Cost** \$93,750

The AC paying behind the visitors center has failed and is in need of replacement. This project would provide for the removal of the damaged paving and installation of new 3" thick AC paving over a compacted base. It may be possible to grind in place the damaged paving and use for base which could reduce project cost.

CRACK FILL / SLURRY SEAL ASPHALT PAVING

Project Index #: 9935SIT3 \$72,000 **Construction Cost**

It is important to maintain the asphalt concrete paving on the site. This project would provide for minor crack filling and slurry sealing of the paving site wide including access roads and parking areas. Striping is included in this estimate. This project should be scheduled on a 5 year cyclical basis to maintain the integrity of the paving and prevent premature failure. 120,000 square feet of asphalt area was used to generate this estimate which includes the new paying in the campgrounds. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

> 25-Jun-15 Page 1 of 17

EXTERIOR FINISHES, SHADE RAMADAS

Project Index #: 9935EXT1 Construction Cost \$3,400

There are steel shade ramadas in different locations throughout the site which measure about 12'x12' each. It is important to maintain the finish, weather resistance and appearance of the structures. This project would provide for painting of the structures.

This project should be done on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/7/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 7/23/2014

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

Priority Class 1: \$47,500 Priority Class 2: \$0 Priority Class 3: \$169,150

Grand Total: \$216,650

25-Jun-15 Page 2 of 17

State of Nevada / Conservation & Natural Resources

RESIDENCE GARAGE #2

SPWB Facility Condition Analysis - 2317

Survey Date: 7/23/2014

RESIDENCE GARAGE #2 BUILDING REPORT

The Residence Garage #2 is a wood framed structure with an asphalt composition roof on a concrete slab-on-grade foundation. It is located along the east side of the residence area and is in good shape.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$4,500

Two to Four Years **Necessary - Not Yet Critical**

EXTERIOR FINISHES

Construction Cost \$4,500 It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, staining, or other applied finishes, and

Project Index #:

Site number: 9935

2317EXT1

caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 3 to 4 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

BUILDING INFORMATION:

Gross Area (square feet): 900

Year Constructed: 2002

Exterior Finish 1: 100 % **Stained Wood Siding**

Exterior Finish 2: 0

Number of Levels (Floors): 1 **Basement?** No

IBC Occupancy Type 1: 100 IBC Occupancy Type 2: 0

Construction Type: Wood Framing

IBC Construction Type: V-B Percent Fire Supressed: 0

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$5.00	Project Construction Cost per Square Foot:	\$0	Priority Class 1:
\$68,000	Total Facility Replacement Construction Cost:	\$4,500	Priority Class 2:
\$75	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
7%	FCNI:	\$4,500	Grand Total:

25-Jun-15 Page 3 of 17 State of Nevada / Conservation & Natural Resources

RESIDENCE GARAGE #1

SPWB Facility Condition Analysis - 2316

Survey Date: 7/23/2014

RESIDENCE GARAGE #1 BUILDING REPORT

The Residence Garage #1 is a wood framed structure with an asphalt composition roof on a concrete slab-on-grade foundation. It is located adjacent to Residence #1 and is in good shape.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$6,720

Necessary - Not Yet Critical Two to Four Years

EXTERIOR FINISHES

Project Index #: 2316EXT1
Construction Cost \$3,360
ding. This project recommends work

Site number: 9935

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 3 to 4 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

INTERIOR FINISHES

Project Index #: 2316INT1 Construction Cost \$3,360

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next two to three years and every 3 to 4 years thereafter to maintain the integrity of the interior of the building. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

BUILDING INFORMATION:

Gross Area (square feet): 672

Year Constructed: 1990

Exterior Finish 1: 100 % Painted Wood Siding

Exterior Finish 2: 0 %

Number of Levels (Floors): 1 Basement? No

IBC Occupancy Type 1: 100 % U IBC Occupancy Type 2: 0 %

Construction Type: Wood Framing

IBC Construction Type: V-B
Percent Fire Supressed: 0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$10.00	Project Construction Cost per Square Foot:	\$0	Priority Class 1:
\$50,000	Total Facility Replacement Construction Cost:	\$6,720	Priority Class 2:
\$75	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
13%	FCNI:	\$6,720	Grand Total:

25-Jun-15 Page 4 of 17

State of Nevada / Conservation & Natural Resources RESTROOM #1

SPWB Facility Condition Analysis - 1602

Survey Date: 7/23/2014

RESTROOM #1 BUILDING REPORT

Restroom #1 is a concrete masonry unit structure with a standing seam metal roof on a concrete foundation. It is located in the north campground loop and is a composting style restroom. The restroom is not ADA accessible.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$1,000

Necessary - Not Yet Critical

Two to Four Years

INTERIOR FINISHES

Project Index #: 1602INT1 Construction Cost \$1,000

Site number: 9935

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next two to three years and every 5 to 7 years thereafter to maintain the integrity of the interior of the building. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

PRIORITY CLASS 3 PROJECTS

Total Construction Cost for Priority 3 Projects: \$1,000

Long-Term Needs

Four to Ten Years

EXTERIOR FINISHES

Project Index #: 1602EXT1 Construction Cost \$1,000

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, block sealing, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 4 to 5 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

BUILDING INFORMATION:

Gross Area (square feet): 200

Year Constructed: 1980

Exterior Finish 1: 100 % Concrete Masonry U

Exterior Finish 2:

Number of Levels (Floors): 1 Basement? No

IBC Occupancy Type 1: 100 % B
IBC Occupancy Type 2: %

Construction Type: Concrete Masonry Units

IBC Construction Type: V-B
Percent Fire Supressed: 0

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$10.00	Project Construction Cost per Square Foot:	\$0	Priority Class 1:
\$20,000	Total Facility Replacement Construction Cost:	\$1,000	Priority Class 2:
\$100	Facility Replacement Cost per Square Foot:	\$1,000	Priority Class 3:
10%	FCNI:	\$2,000	Grand Total:

25-Jun-15 Page 5 of 17

State of Nevada / Conservation & Natural Resources RESTROOM #3

SPWB Facility Condition Analysis - 1316

Survey Date: 7/23/2014

RESTROOM #3 BUILDING REPORT

Restroom #3 is a concrete masonry unit structure with a standing seam metal roof on a concrete foundation. This restroom contains showers as well a toilet rooms for men and women. It is located in the south campground loop. The restroom is somewhat ADA compliant but is in need of some modifications. A fish cleaning station is also part of this facility.

PRIORITY CLASS 1 PROJECTS

Total Construction Cost for Priority 1 Projects: \$5,000

Site number: 9935

Currently Critical Immediate to Two Years

ADA IMPROVEMENTS Project Index #: 1316ADA2
Construction Cost \$5,000

The existing restrooms and parking area are in need of some minor ADA accessibility upgrades. This project would provide for a no parking sign to be installed at the access isle, restroom signage, plumbing jackets on the sinks, and the installation of grab bars in the restroom containing the ADA accessible shower. The 2012 IBC, ICC/ANSI A117.1 - 2009, NRS 338.180 and the most current version of the ADA Standards For Accessible Design were used as a reference for this project.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$8,640

Necessary - Not Yet Critical Two to Four Years

Project Index #: 1316EXT1
EXTERIOR FINISHES Construction Cost \$4,320

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, block sealing, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 2 to 3 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

Project Index #: 1316INT1
INTERIOR FINISHES Construction Cost \$4,320

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next two to three years and every 2 to 3 years thereafter to maintain the integrity of the interior of the building. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

25-Jun-15 Page 6 of 17

BUILDING INFORMATION:

Gross Area (square feet): 400

Year Constructed: 1982

Exterior Finish 1: 100 % Concrete Masonry U

Exterior Finish 2: %

Number of Levels (Floors): 1 Basement? No

IBC Occupancy Type 1: 100 % B IBC Occupancy Type 2: %

Construction Type: Concrete Masonry Units

IBC Construction Type: V-B
Percent Fire Supressed: 0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$34.10	Project Construction Cost per Square Foot:	\$5,000	Priority Class 1:
\$80,000	Total Facility Replacement Construction Cost:	\$8,640	Priority Class 2:
\$200	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
17%	FCNI:	\$13,640	Grand Total:

25-Jun-15 Page 7 of 17

State of Nevada / Conservation & Natural Resources PARK OFFICE / SHOP

SPWB Facility Condition Analysis - 1315

Survey Date: 7/23/2014

PARK OFFICE / SHOP BUILDING REPORT

The Park Office / Shop is a wood framed, concrete foundation, and standing seam metal roof structure which contains offices, a restroom, visitor center and shop areas for park personnel. The restroom is somewhat ADA compliant and there is a designated ADA accessible entrance into the building. Heating is provided by an old propane fired forced air unit and the shop has old radiant heaters and a wood burning device. The pressure tank and water treatment system is located in this structure.

PRIORITY CLASS 1 PROJECTS

Total Construction Cost for Priority 1 Projects: \$25,500

Project Index #:

Project Index #:

Project Index #:

Construction Cost

Construction Cost

Construction Cost

Site number: 9935

1315ADA1

1315SFT2

1315SFT3

\$3,500

\$17,000

\$5,000

Currently Critical Imm

Immediate to Two Years

ADA PARKING UPGRADE

The Americans with Disabilities Act (ADA) provides for accessibility to sites and services for people with physical limitations. The main entrance to the building has an ADA parking stall which does not entirely meet the requirements of the code. This project provides funding to bring the existing ADA parking area up to code including a compliant path of travel from the parking space to the building entrance, updated signage and any other necessary upgrades. The 2012 IBC, ICC/ANSI A117.1 - 2009, NRS 338.180 and the most current version of the ADA Standards For Accessible Design were used as a reference for this project. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

FIRE ALARM SYSTEM INSTALLATION

This building is lacking a fire alarm and detection system. It is recommended that a fire detection and alarm system be installed. When completed, the new system will provide visual, as well as audible notification, in accordance with ADA requirements located in ICC/ANSI A117.1- 2009 Section 7 and the 2012 International Fire Code. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

INSTALL EXIT SIGNS AND EGRESS LIGHTING

The building does not have any exit signs or emergency lighting. This project would provide for the purchase and installation of self-illuminated or LED style exit signs with battery-backed internal systems as well as emergency exit lighting to provide illumination along the egress route. IBC - 20012 Chapter 10 was referenced for this project. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

25-Jun-15 Page 8 of 17

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$120,600

Project Index #:

Project Index #:

Construction Cost

Construction Cost

1315SFT1

1315EXT3

\$24,000

\$47,600

Necessary - Not Yet Critical Two to Four Years

Project Index #: 1315EXT1
EXTERIOR FINISHES Construction Cost \$17,000

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 2 to 3 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

HVAC UPGRADE Project Index #: 1315HVA1
Construction Cost \$6,000

The building is heated by a propane fired forced air unit installed in 1982. It is original to the building and has reached the end of its expected life. This project would provide for replacement of the heater and includes removal and disposal of the existing unit and all required connections to utilities. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

INSTALL FIRE SUPPRESSION SYSTEM

This building does not have an automatic fire suppression system. Nevada State Fire Marshal NAC 477.915 (c) requires buildings having a floor area exceeding 12,000 s.f. on any floor or 24,000 s.f. on all floors, or which contain a B or R-1 occupancy, be scheduled for installation of an automatic fire suppression system during the next remodeling of, or addition to the building. Backflow prevention is included in this estimate. This building is partially classified as a B occupancy. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

Project Index #: 1315INT1
INTERIOR FINISHES Construction Cost \$17,000

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next two to three years and every 5 to 7 years thereafter to maintain the integrity of the interior of the building. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

REPLACE OVERHEAD COILING DOORS

There are four 12'x10' overhead coiling doors which are damaged and do not function properly. They are original to the building and should be scheduled for replacement. This project would provide for the removal and disposal of the manually operated overhead coiling doors and replacement with two motorized doors. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

WINDOW REPLACEMENT Project Index #: 1315EXT2 Construction Cost \$9,000

There are six windows in the building approximately 3'x7' with an exposed bottom edge less than 18" above the floor. IBC 2012 - Section 2406 requires these windows to have safety glass labeled due to their hazardous location. This project recommends replacing the windows with safety glazed windows. This estimate is for the replacement of 6 units. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

25-Jun-15 Page 9 of 17

BUILDING INFORMATION:

Gross Area (square feet): 3,400

Year Constructed: 1982

Exterior Finish 1: 100 % Painted Wood Siding

Exterior Finish 2: %

Number of Levels (Floors): 1 Basement? No

IBC Occupancy Type 1: 40 % B
IBC Occupancy Type 2: 60 % S-2

Construction Type: Wood Framing

IBC Construction Type: V-B Percent Fire Supressed: 0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$42.97	Project Construction Cost per Square Foot:	\$25,500	Priority Class 1:
\$765,000	Total Facility Replacement Construction Cost:	\$120,600	Priority Class 2:
\$225	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
19%	FCNI:	\$146,100	Grand Total:

25-Jun-15 Page 10 of 17

State of Nevada / Conservation & Natural Resources RESTROOM #2

SPWB Facility Condition Analysis - 1314

Survey Date: 7/23/2014

RESTROOM #2 BUILDING REPORT

Restroom #2 is a concrete masonry unit and wood framed structure with a standing seam metal roof. This restroom is located in the day use picnic area. It is a Clivus composting toilet in good condition. The restroom is not ADA compliant.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$5,070

Site number: 9935

410 00

Necessary - Not Yet Critical Two to Four Years

Project Index #: 1314EXT1
EXTERIOR FINISHES

Construction Cost \$2,535

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, block sealing, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 2 to 3 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

Project Index #: 1314INT1
INTERIOR FINISHES
Construction Cost \$2,535

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next two to three years and every 5 to 7 years thereafter to maintain the integrity of the interior of the building. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

BUILDING INFORMATION:

Gross Area (square feet): 507

Year Constructed: 1982

Exterior Finish 1: 100 % Concrete Masonry U

Exterior Finish 2: %

Number of Levels (Floors): 1 Basement? No

IBC Occupancy Type 1: 100 % B

IBC Occupancy Type 2: %

Construction Type: Concrete Masonry Unit Framing

IBC Construction Type: V-B
Percent Fire Supressed: 0

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$10.00	Project Construction Cost per Square Foot:	\$0	Priority Class 1:
\$51,000	Total Facility Replacement Construction Cost:	\$5,070	Priority Class 2:
\$100	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
10%	FCNI:	\$5,070	Grand Total:

25-Jun-15 Page 11 of 17

State of Nevada / Conservation & Natural Resources RESIDENCE #2

SPWB Facility Condition Analysis - 1313

Survey Date: 7/23/2014

RESIDENCE #2 BUILDING REPORT

Residence #2 is a wood framed structure on a concrete foundation. It has a standing seam metal roof and a full basement. It contains living quarters for park personnel which includes a kitchen and dining area, bedrooms, restrooms and a partially finished basement

PRIORITY CLASS 1 PROJECTS

Total Construction Cost for Priority 1 Projects: \$4,000

Project Index #:

Project Index #:

Project Index #:

Construction Cost

Construction Cost

Construction Cost

Site number: 9935

1313SFT2

1313EXT1

1313HVA1

\$4,800

\$11,520

\$4,000

Currently Critical

Immediate to Two Years

REMODEL FRONT ENTRY / STAIRWAY

The existing front entry to the residence has a non conforming stairway and landing. The entry floor is cantilevered above grade and is supported by two posts sitting on an exposed concrete pier. This project would provide for a new concrete pier / foundation support for the floor and new landing and stairs, wood framed stairs with handrails and a concrete slab-on-grade landing at the bottom. The other entry is similar and is also recommended to be replaced. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$46,440

Necessary - Not Yet Critical

Two to Four Years

EXTERIOR FINISHES

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 3 to 4 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

HVAC REPLACEMENT

There is an existing propane fired furnace that is approaching 20 years old and is in need of replacement. This project would provide for the removal and disposal of the old unit and installation of a new propane gas fired furnace including all required connections to existing utilities. Cleaning of the existing ductwork is also included in this estimate.

INTERIOR FINISHES

Project Index #: 1313INT1 Construction Cost \$11,520

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next two to three years and every 3 to 4 years thereafter to maintain the integrity of the interior of the building. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

25-Jun-15 Page 12 of 17

REPAIR VINYL SIDING

Project Index #: 1313EXT2
Construction Cost \$2,400

The north side of the building had an attached carport that has since been removed. The vinyl siding was installed before the carport was removed and the siding does not extend up the entire wall. This project recommends removing the old wood siding at the gable end and installing vinyl siding to match the rest of the building. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

Project Index #: 1313INT3
REPLACE FLOORING Construction Cost \$7,200

The existing carpet and vinyl flooring has reached the end of it's useful life. This project would provide for the removal and disposal of the existing flooring and installation of new vinyl and carpet flooring throughout the residence.

Project Index #:

Construction Cost

1313ENR1

\$9,000

WINDOW REPLACEMENT

The existing windows are old aluminum dual pane type and are in need of replacement. This project would provide for the removal and disposal of the existing windows and installation of new vinyl dual pane window units. A total of 9 window units was used for this estimate.

BUILDING INFORMATION:

Gross Area (square feet): 2,304

Year Constructed: 1982

Exterior Finish 1: 100 % Vinyl Siding

Exterior Finish 2: %

Number of Levels (Floors): 1 Basement? Yes

IBC Occupancy Type 1: 100 % R-3

IBC Occupancy Type 2: %

Construction Type: Wood Framing

IBC Construction Type: V-B
Percent Fire Supressed: 0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$21.89	Project Construction Cost per Square Foot:	\$4,000	Priority Class 1:
\$403,000	Total Facility Replacement Construction Cost:	\$46,440	Priority Class 2:
\$175	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
13%	FCNI:	\$50,440	Grand Total:

25-Jun-15 Page 13 of 17

State of Nevada / Conservation & Natural Resources RESIDENCE #1

SPWB Facility Condition Analysis - 1312

Survey Date: 7/23/2014

RESIDENCE #1 BUILDING REPORT

Residence #1 is a wood framed structure on a concrete foundation. It has a standing seam metal roof and a full basement. It contains living quarters for park personnel which includes a kitchen and dining area, bedrooms and restrooms.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$44,040

Necessary - Not Yet Critical Two to Four Years

iccessary - Not let Chicai wo to rour rears

Project Index #: 1312EXT1
EXTERIOR FINISHES Construction Cost \$11,520

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 2 to 3 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

HVAC REPLACEMENT

Project Index #: 1312HVA1 Construction Cost \$4,800

Site number: 9935

There is an existing propane fired furnace that is approaching 20 years old and is in need of replacement. This project would provide for the removal and disposal of the old unit and installation of a new propane gas fired furnace including all required connections to existing utilities. Cleaning of the existing ductwork is also included in this estimate.

Project Index #: 1312INT1
INTERIOR FINISHES Construction Cost \$11,520

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next two to three years and every 5 to 7 years thereafter to maintain the integrity of the interior of the building. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

REPLACE FLOORING Project Index #: 1312INT2
Construction Cost \$7,200

The existing carpet and vinyl flooring has reached the end of it's useful life. This project would provide for the removal and disposal of the existing flooring and installation of new vinyl and carpet flooring throughout the residence.

WINDOW REPLACEMENT Project Index #: 1312ENR1
Construction Cost \$9,000

The existing windows are old aluminum dual pane type and are in need of replacement. This project would provide for the removal and disposal of the existing windows and installation of new vinyl dual pane window units. A total of 9 window units was used for this estimate.

25-Jun-15 Page 14 of 17

BUILDING INFORMATION:

Gross Area (square feet): 2,304

Year Constructed: 1982

Exterior Finish 1: 100 % Painted Wood Siding

Exterior Finish 2: %

Number of Levels (Floors): 1 Basement? Yes

IBC Occupancy Type 1: 100 % R-3

IBC Occupancy Type 2:

Construction Type: Wood and Concrete Framing

IBC Construction Type: V-B
Percent Fire Supressed: 0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$19.11	Project Construction Cost per Square Foot:	\$0	Priority Class 1:
\$403,000	Total Facility Replacement Construction Cost:	\$44,040	Priority Class 2:
\$175	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
11%	FCNI:	\$44.040	Grand Total:

25-Jun-15 Page 15 of 17

State of Nevada / Conservation & Natural Resources

UTILITY SHED

SPWB Facility Condition Analysis - 1311

Survey Date: 7/23/2014

UTILITY SHED BUILDING REPORT

The Utility Shed is a portable steel storage building. It is located in the Park Office yard adjacent to the fueling tanks. It is in fair shape.

PRIORITY CLASS 2 PROJECTS

Total Construction Cost for Priority 2 Projects: \$200

Site number: 9935

Necessary - Not Yet Critical Two to Four Years

Project Index #: 1311EXT1
EXTERIOR FINISHES Construction Cost \$200

It is important to maintain the finish, weather resistance and appearance of the building. This project recommends work to protect the exterior building envelope, other than the roof, including painting, staining, or other applied finishes, and caulking around windows, flashing, fixtures, and other penetrations to maintain the building in good, weather tight condition. It is recommended that this project be implemented in the next 2 to 3 years and is recommended on a cyclical basis based on environmental conditions. This project or a portion thereof was previously recommended in the FCA report dated 11/07/2007. It has been amended accordingly to reflect conditions observed during the most recent survey date of 07/23/2014.

BUILDING INFORMATION:

Gross Area (square feet): 200

Year Constructed: 1982

Exterior Finish 1: 100 % Metal Siding

Exterior Finish 2: %

Number of Levels (Floors): 1 Basement? No

IBC Occupancy Type 1: 100 % S-2

IBC Occupancy Type 2: %

Construction Type: Portable Steel Building

IBC Construction Type: V-B
Percent Fire Supressed: 0 %

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

\$1.00	Project Construction Cost per Square Foot:	\$0	Priority Class 1:
\$4,000	Total Facility Replacement Construction Cost:	\$200	Priority Class 2:
\$20	Facility Replacement Cost per Square Foot:	\$0	Priority Class 3:
5%	FCNI:	\$200	Grand Total:

25-Jun-15 Page 16 of 17

NOTES:

The deficiencies outlined in this report were noted from a visual survey. The costs do not represent the cost of a complete facility renovation or maintenance needs. Recommended projects do not include telecommunications, furniture, window treatment, space change, program issues, relocation, swing space, or costs that could not be identified or determined from the survey and available building

Individual projects and costs noted herein may be impacted by new construction materials or methods, agency projects, and pending or proposed Capital Improvement Projects (CIP).

This report was created under the authority found in NRS 341.201 by the State Public Works Board and should be utilized as a planning level document.

REPORT DEVELOPMENT:

State Public Works Board 515 E. Musser Street, Suite 102 (775) 684-4141 voice Facilities Condition Analysis Carson City, Nevada 89701-4263 (775) 684-4142 facsimile

25-Jun-15 Page 17 of 17



Wild Horse State Recreation Area Site – FCA Site #9935 Description: AC paving in need of removal and replacement.



Boat Inspection Station – FCA Building #3303 Description: Exterior of the structure.



Typical Ramada – FCA Building - Multiple Numbers Description: Exterior of the shade structure.



Residence Garage #2 – FCA Building #2317 Description: Exterior of the structure.



Residence Garage #1 – FCA Building #2316 Description: Exterior of the garage.



Restroom #1 – FCA Building #1602 Description: Exterior of the restroom.



Restroom #3 – FCA Building #1316 Description: Exterior of the restroom.



Park Office / Shop – FCA Building #1315
Description: Exterior of the office and public entrance.



Park Office / Shop – FCA Building #1315 Description: View of the restroom.



Restroom #2 – FCA Building #1314 Description: Exterior of the restroom.



Residence #2 – FCA Building #1313 Description: Exterior of the building.



Residence #1 – FCA Building #1312 Description: Exterior of the building.



Utility Shed – FCA Building #1311 Description: Exterior of the building.