

STATE OF NEVADA

DEPARTMENT OF ADMINISTRATION STATE PUBLIC WORKS DIVISION FACILITY CONDITION ASSESSMENT

PROPERTY PORTFOLIO REVIEW FACILITY INSIGHTS

NORTHWEST REGION

9902 - NDOW WESTERN REGION FALLON OFFICE SITE 380 W B ST FALLON, NV 89406-2916 CHURCHILL COUNTY

SURVEY DATE: 01/11/2023



TABLE OF CONTENTS

INTRODUCTION	3	
KEY FINDINGS	4	
OVERALL RECOMMENDATIONS		4
SITE UTILITIES AND INFRASTRUCTURE SAFETY, COMPLIANCE AND ACCESSIBILITY ENVIRONMENTAL LANDSCAPING CONCERNS		4
PROPERTY MAP, 380 W B ST, FALLON	6	
PROPERTY SNAPSHOT, NDOW WESTERN REGION FALLON OFFICE SITE	7	
FACILITY DETAILS, WESTERN REGION FALLON FIELD OFFICE	8	
FACILITY DETAILS, DEPT. OF WILDLIFE BOAT STORAGE FACILITY	9	
APPENDIX A - FACILITY CONDITION INDEX (FCI)	10	
APPENDIX B — SUPPLEMENTARY PHOTOGRAPHIC RECORD	11	
BUILDING SYSTEMS EXTERIOR INTERIOR		12
APPENDIX C – REPORT DISTRIBUTION	14	
DIVISIONAL CONTACTS		
APPENDIX D - FCA RESOURCES	15	
APPENDIX E – REVISION HISTORY	16	

The **FCA PROGRAM**, established by the State Public Works Division (SPWD), fulfills oversight responsibilities under **NRS 341.128** (periodically inspect state-owned institutions) and **NRS 331.110** (inventory of state property).

The **Property Portfolio Review** is a two-part evaluation offering an assessment of a property's condition and prioritized project recommendations with preliminary cost estimates.

INTRODUCTION

The **Facility Insights** report serves as the foundation of the **Property Portfolio Review**, evaluating the property and its facilities. The Project Addendum, part two, builds on this foundation by detailing specific projects and their preliminary cost estimates, excluding soft costs (e.g., consultant fees, permits, furnishings).

This report emphasizes the Facility Condition Index (FCI, see Appendix A), a critical metric used to assess the overall health, functionality, and maintenance priorities of each facility. The observations and data in this report are based on a visual assessment conducted at the time of the review and reflect the conditions observed.

The data in this report was gathered through the following methods:

- Research: Historical data of past repairs and improvements. Current trends in energy enhancements.
- Document Review: Examination of building plans, maintenance logs, and previous reports.
- Interviews: Consultations with key stakeholders to gather insights.
- Site Visit: Visual and photographic inspection of the site and facilities. Inspections include review of building systems such as fire alarm, electrical and HVAC systems as well as interior and exterior finishes, roofing systems, paving and landscape.



Disclaimer: Observations are limited to **accessible areas** and conditions present during the survey. **Accurate Forecasting**: Updated estimates must be obtained that include soft costs and professional evaluations.

KEY FINDINGS

OVERALL RECOMMENDATIONS

The following recommendations address the primary concerns identified during the assessment and prioritize actions for the site and building.

Property: The overall condition of the site is classified as FAIR derived from the average FCI of its buildings. Investment is needed to repair & improve security in the rear parking area including paving, fencing and site lighting improvements.

OVERALL SITE CONDITION

- Infrastructure: Well maintained, with adequate drainage and accessibility. Paved areas, including parking lots and walkways show signs of wear in the rear parking.
- Findings: Key issues were identified that will require upgrade.
 - Seismic gas valve needed.
 - o Domestic hot water recirculating plumbing is needed.
 - Partial wall framing needs completion.
 - o Window replacement for increased energy efficiency.

SITE UTILITIES AND INFRASTRUCTURE

- Water Supply and Plumbing: Insufficient, domestic hot water improvements needed.
- ° Electrical Systems: Modern, no issues noted.
- ° Stormwater Drainage: Adequate, no concerns noted.

SAFETY, COMPLIANCE AND ACCESSIBILITY

- Accessibility: The site is compliant with current ADA and safety standards.
- ° Fire Safety: Adequate systems across the site. Fire extinguishers mounted throughout.

ENVIRONMENTAL LANDSCAPING CONCERNS

Landscaping and Green Space Management: The condition of the landscaping is well maintained. Some buildup of combustible debris were noted on the north side of the Boat Storage Facility.

PROPERTY MAP, 380 W B ST, FALLON



TOTAL # OF BLDGS NORTHWEST REGION
380 W B ST
2 FALLON, NV 89406-2916
CHURCHILL COUNTY


SITE	BLDG	NAME	STATUS	
9902	0633	WESTERN REGION FALLON FIELD OFFICE	OCCUPIED	ı
9902	1438	DEPT. OF WILDLIFE BOAT STORAGE FACILITY	OCCUPIED	
9902	9902	NDOW WESTERN REGION FALLON OFFICE SITE	OCCUPIED	

PROPERTY SNAPSHOT, NDOW WESTERN REGION FALLON OFFICE SITE



	9902 NDOW WESTERN REGION FALLON OFFICE SITE
STATUS:	OCCUPIED
PARCEL SIZE:	0.320 ACRE(S)
HARDSCAPE:	212.000 SF CFW
LOCATION:	APN: 001-141-02 LAT/LONG: 39.47788, -118.78119
USAGE:	SITE-GENERAL
# OF BLDGS:	2
ADDR:	NORTHWEST REGION 380 W B ST FALLON, NV 89406-2916 CHURCHILL COUNTY
OCC / MAINT:	DEPARTMENT - NDOW DEPT OF WILDLIFE

SITE INDEPENDENT OF A COMPLEX



FACILITY DETAILS, WESTERN REGION FALLON FIELD OFFICE






PROJECT DATA

for men and women, a conference room, and office

space.



FACILITY DETAILS, DEPT. OF WILDLIFE BOAT STORAGE FACILITY





PROJECT DATA

STATUS	#	COST	PRI	#	COST
DEFERRED	1	\$4,500	2	1	\$4,500
NEW	1	\$4,500	3	1	\$4,500
TOTAL	2	\$9,000	TOTAL	2	\$9,000
	PROJECTS	BY TYPE		PROJECT B	Y PRIORITY
\$4,500 -			3 \$4,50	0	2 \$4,500
		● ELE ● EXT			•2 •3

APPENDIX A - FACILITY CONDITION INDEX (FCI)

• What It Is: A widely used critical metric to evaluate the overall health, functionality, and maintenance priorities of each facility

- Purpose:
 - Provides a quick snapshot of a facility's health, expressed as a percentage
 - Lower FCI Values:
 - 0.05: Indicates a facility is good condition
 - 0.6 0.10: Indicates a facility is in fair condition
 - Higher FCI Values:
 - 0.11 0.30: Indicates a facility is in poor condition
 - 0.30: Indicates a facility is in critical condition
- Use Cases:
 - · Helps prioritize repairs
 - Guides funding allocation by comparing conditions across multiple facilities in a portfolio
- Calculation: FCI = Cost of necessary repairs or Deferred Maintenance

 Current Replacement Value
- Example: The facility's replacement cost is \$11,540,000, and the required repairs total \$2,236,200, resulting in an FCI of 19% (0.19)

APPENDIX B – SUPPLEMENTARY PHOTOGRAPHIC RECORD

BUILDING SYSTEMS







EXTERIOR









INTERIOR











APPENDIX C - REPORT DISTRIBUTION

DIVISIONAL CONTACTS

DEPT	TITLE	
WILDLIFE	DIRECTOR	
WILDLIFE	DEPUTY DIRECTOR	
WILDLIFE	DEPUTY DIRECTOR	
WILDLIFE	SUPERVISOR, PROFESSIONAL ENGINEER	
WILDLIFE ADMINISTRATIVE ASSISTANT 2		

STATEWIDE CONTACTS CC'D

The following positions across various departments are CC'D:

- GFO Budget
 - Executive Branch Budget Officer
- DCNR Lands Division
 - Division Administrator
 - Deputy Division Administrator
- Legislative Counsel Bureau
 - Senior Program Analyst
 - Principal Program Analyst

- Administration Risk Management Division
 - Division Administrator
 - Insurance/Loss Prevention Specialist
 - Program Officer
 - Management Analyst 4
 - Safety Specialist Consultant

APPENDIX D - FCA RESOURCES



KEN FORBES

Construction Project Coordinator III kforbes@admin.nv.gov
775.315-5573

CAROL MYERS

Construction Project Coordinator II mc.myers@admin.nv.gov 775.690-5134

YADHIRA PIMENTEL

Administrative Assistant IV mypimentel@admin.nv.gov 775.684-4126

APPENDIX E – REVISION HISTORY

VERSION	DATE	AMENDMENT
0	1/29/2025	Initial.