State of Nevada Department of Wildlife

LAUGHLIN WILDLIFE FIELD OFFICE

1595 Casino Drive Laughlin, Nevada 89029

Site Number: 9838 STATE OF NEVADA PUBLIC WORKS DIVISION FACILITY CONDITION ANALYSIS



Report distributed in January 2023

State of Nevada Department of Wildlife

The Facility Condition Analysis Program was created under the authority found in NRS 341.128. The State Public Works Division develops this report using cost estimates based on contractor pricing which includes materials, labor, location factors and profit and overhead. The costs of project design, management, special testing and inspections, inflation and permitting fees are not included. Cost estimates are derived from the R.S. Means Cost Estimating Guide and from comparable construction costs of projects completed by SPWD project managers.

The deficiencies outlined in this report were noted from a visual survey. This report does not address routine maintenance needs. Recommended projects do not include telecommunications, furniture, window treatments, space change, program issues, or costs that could not be identified or determined from the survey and available building information. If there are buildings without projects listed, this indicates that only routine maintenance needs were found. This report considers probable facility needs for a 10 year planning cycle.

This report is not a guarantee of funding and should not be used for budgeting purposes. This report is a planning level document for agencies and State Public Works Division to assess the needs of the Building and/or Site and to help support future requests for ADA upgrades / renovations, Capital Improvement Projects, and maintenance. The final scope and estimate of any budget request should be developed by a qualified individual. Actual project costs will vary from those proposed in this report when the final scope and budget are developed.

Establishing a Facility Condition Needs Index (FCNI) for each building

The FCA reports identify maintenance items and establish construction cost estimates. These costs are summarized at the end of the report and noted as construction costs per square foot. A FCNI is commonly used by facility managers to make a judgment whether to recommend whole replacement of facilities, rather than expending resources on major repairs and improvements. The FCNI is a ratio between the proposed facility upgrade costs and facility replacement costs (FRC). Those buildings with indices greater than .50 or 50% are recommended to be considered for complete replacement.

Class Definitions

PRIORITY CLASS 1 - Currently Critical (Immediate to Two Years)

Projects in this category require immediate action to return a facility to normal operation, stop accelerated deterioration, correct a fire/life safety hazard, or correct an ADA requirement.

PRIORITY CLASS 2 - Necessary - Not Yet Critical (Two to Four Years)

Projects in this category include conditions requiring appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further.

PRIORITY CLASS 3 - (Four to Ten Years)

Projects in this category include items that represent a sensible improvement to existing conditions. These items are not required for the most basic function of a facility; however, Priority 3 projects will either improve overall usability and/or reduce long-term maintenance.

Site number: 9838		Facility Condition Nee	Cost to	Cost to	Cost to	Total Cost	Cost to				
Index #	Building Name	_	Sq. Feet	Yr. Built	Survey Date	Repair: P1	Repair: P2	Repair: P3	to Repair	Replace	FCNI
2470	LAUGHLIN WILDLIFE	FIELD OFFICE	2700	2004	4/18/2022	\$10,000	\$19,600	\$27,000	\$56,600	\$1,215,000	5%
	1595 Casino Drive	Laughlin									
9838	LAUGHLIN WILDLIFE	FIELD OFFICE SITE		0	4/18/2022	\$0	\$34,600	\$0	\$34,600		0%
	1595 Casino Drive	Laughlin									
4278	SHADE STRUCTURE		2600	2012	4/18/2022	\$0	\$0	\$0		\$130,000	
	1595 Casino Drive	Laughlin									
		Report Totals:	5,300			\$10,000	\$54,200	\$27,000	\$91,200	\$1,345,000	7%

Acronym	Definition
Building Codes, Laws, Regulations and Guidelines	
AHJ	Authority Having Jurisdiction
AWWA	American Water Works Association
HVAC	Heating, Ventilating & Air Conditioning
IBC	International Building Code
ICC	International Code Council
IEBC	International Existing Building Code
IECC	International Energy Conservation Code
IFC	International Fire Code
IFGC	International Fuel Gas Code
IRC	International Residential Code
NFPA	National Fire Protection Association
NEC	National Electrical Code
OSHA	Occupational Safety and Health Administration
SAD	Standards for Accessible Design
SMACNA	Sheet Metal and Air Conditioning Contractors
	National Association
UMC	Uniform Mechanical Code
UPC	Uniform Plumbing Code
State of Nevada	
CIP	Capital Improvement Project
FCA	Facility Condition Analysis
FCNI	Facility Condition Needs Index
FRC	Facility Replacement Cost
NAC	Nevada Administrative Code
NDEP	Nevada Department of Environmental Protection
NRS	Nevada Revised Statutes
SFM	State Fire Marshal
SHPO	State Historic Preservation Office
SPWD	State Public Works Division
Miscellaneous	
DDC	Direct Digital Controls
FRP	Fiberglass Reinforced Plastic
GFCI	Ground Fault Circuit Interrupter
LED	Light Emitting Diode
PRV	Pressure Regulating Valve
TDD	Telecommunications Device for the Deaf
VCT	Vinyl Composite Tile

Acronyms List

This is a generic acronym list of commonly used terms throughout the Facility Condition Analysis report.

SPWD Facility Condition Analysis

Table of Contents

Building Name	Index #	
LAUGHLIN WILDLIFE FIELD OFFICE SITE	9838	
SHADE STRUCTURE	4278	No Current Projects
LAUGHLIN WILDLIFE FIELD OFFICE	2470	

State of Nevada / Dept of Wildlife LAUGHLIN WILDLIFE FIELD OFFICE SITE SPWD Facility Condition Analysis - 9838 Survey Date: 4/18/2022

BUILDING REPORT

The Department of Wildlife Field Office is located on about 1-1/2 acres in Laughlin, Nevada. The site has paved public and employee parking including ADA accessible parking and route of travel into the office. The rear of the site is mainly a storage area with a covered metal parking structure. The site is mostly paved. The site is fenced and is served by public utilities, including water and sewer. The site is well maintained.

PRIORITY CLASS 2 PROJECTS	Total Construction Cost for Priority 2 Projects:	\$34.600
I KIOKII I CLASS ZI KOJECIS	Total Construction Cost for Thorney 2 Trojects.	\$37,000

Necessary - Not Yet Critical Two to Four Years

CRACK FILL & SEAL ASPHALT PAVING

It is important to maintain the asphalt concrete paving on the site. This project would provide for minor crack filling and sealing of the paving site wide including access roads, parking areas, and vehicle storage areas. Striping is included in this estimate. This project should be scheduled on a 5 year cyclical basis to maintain the integrity of the paving and prevent premature failure. 32,000 square feet of asphalt area was used to generate this estimate. This project or a portion thereof was previously recommended in the FCA report dated 04/11/2012. It has been amended accordingly to reflect conditions observed during the most recent survey date of 04/18/2022.

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

Priority Class 1:	\$0
Priority Class 2:	\$34,600
Priority Class 3:	\$0
Grand Total:	\$34,600

Project Index #: 9838SIT1 Construction Cost \$34,600 State of Nevada / Dept of WildlifeLAUGHLIN WILDLIFE FIELD OFFICESPWD Facility Condition Analysis - 2470Survey Date:4/18/2022

LAUGHLIN WILDLIFE FIELD OFFICE BUILDING REPORT

The Laughlin Wildlife Field Office is a concrete masonry unit building with a single-ply roofing system on a concrete foundation. The roofing was replaced in 2010 with a 20 year warranty. The facility contains a public reception area, restrooms, including a unisex ADA compliant restroom for the public, and a kitchen/sleeping area for staff. Adjacent to the office space is a large apparatus bay for vehicles and equipment storage. There is a fire alarm system and the HVAC system consists of 2 roof mounted evaporative cooling units over the apparatus bay and 2 roof mounted packaged heat pump units for the office areas. The heat pumps were replaced in 2021.

PRIORITY CLASS 1 PROJECTS	Total Construction Cost for Priority 1 Projects:	\$10,000
Currently Critical	Immediate to Two Years	

ARC FLASH and ELECTRICAL COORDINATION STUDY

Arc flash and electrical breaker coordination studies have not been performed or it has been more than 5 years since the last coordination study. Safety requirements for maintenance personnel and the latest electrical code require coordination studies to be verified and performed every 5 years, along with arc flash labeling on all electrical panels. Additionally, the exterior main service panel show evidence of recent breaker installation. This study will ensure that the new breakers are properly rated for the main service panel. This project will perform the required coordination study, evaluation, adjustments and labeling for the building's electrical distribution system.

PRIORITY CLASS 2 PROJECTS	Total Construction Cost for Priority 2 Projects:	\$19,600

Necessary - Not Yet Critical Two to Four Years

CEILING REPAIRS

Two locations on the interior drywall ceiling were damaged and should be scheduled for repair. It appears that old roof leaks were the cause based on pictures taken of the same damage during the previous FCA Survey in 2012. The roofing was replaced in 2010 prior to the 2012 Survey and the ceiling damage has not worsened since then. This project would provide for repair of the gypsum board ceiling and include tape, mud, texture and paint.

FLOORING REPLACEMENT

The vinyl floor coverings in this building were generally in poor condition and have reached the end of their serviceable lives. This project would provide funding to completely remove the existing flooring and replace with durable sheet vinyl.

PRIORITY CLASS 3 PROJECTS

Long-Term Needs

EXTERIOR FINISHES

Four to Ten Years

Project Index #: Construction Cost

Total Construction Cost for Priority 3 Projects:

The exterior finishes were in fair condition at the time of the survey. It is important to maintain the finish, weather resistance, and appearance of the building. This project would provide funding to protect the exterior of the building excluding the roof. Included in the cost is power washing, priming and painting of the EIFS and caulking of the windows. flashing, fixtures and all other penetrations. It is recommended that the building be painted in the next 4 - 6 years and that this project be scheduled on a cyclical basis to maintain the integrity of the structure.

Project Index #: 2470ELE1 Construction Cost \$10,000

Construction Cost\$7,500or repair. It appears that old roof

Project Index #:

2470INT3

\$27,000

\$13,500

2470EXT1

Project Index #: 2470INT2 Construction Cost \$12,100

INTERIOR FINISHES

Project Index #: 2470INT1 Construction Cost \$13,500

The interior finishes are in fair condition. It is recommended that the interior walls and ceilings be painted at least once in the next 4 - 6 years and that this project be scheduled on a cyclical basis to maintain the integrity of the structure. Prior to painting, all surfaces should be repaired and prepped. An epoxy-based paint should be utilized in wet areas for durability.

BUILDING INFORMATION:

Gross Area (square feet):				IBC Occupancy Type 1:		
Year Constructed:	2004			IBC Occupancy Type 2:	30	% S-2
Exterior Finish 1:	50	%	Painted Stucco / EIFS	Construction Type:	Con	crete Masonry Units and wood
Exterior Finish 2:	50	%	Painted CMU	IBC Construction Type:	V-B	•
Number of Levels (Floors):	1]	Basement? No	Percent Fire Suppressed:	0	%

PROJECT CONSTRUCTION COST TOTALS SUMMARY:

Priority Class 1:	\$10,000	Project Construction Cost per Square Foot:	\$20.96
Priority Class 2:	\$19,600	Total Facility Replacement Construction Cost:	\$1,215,000
Priority Class 3:	\$27,000	Facility Replacement Cost per Square Foot:	\$450
Grand Total:	\$56,600	FCNI:	5%

NOTES:

The deficiencies outlined in this report were noted from a visual survey. The costs do not represent the cost of a complete facility renovation or maintenance needs. Recommended projects do not include telecommunications, furniture, window treatment, space change, program issues, relocation, swing space, or costs that could not be identified or determined from the survey and available building information.

Individual projects and costs noted herein may be impacted by new construction materials or methods, agency projects, and pending or proposed Capital Improvement Projects (CIP).

This report was created under the authority found in NRS 341.128 by the State Public Works Division and should be utilized as a planning level document.

REPORT DEVELOPMENT:

State Public Works Division	515 E. Musser Street, Suite 102	(775) 684-4141 voice
Facilities Condition Analysis	Carson City, Nevada 89701-4263	(775) 684-4142 facsimile



Laughlin Wildlife Field Office Site – FCA Site #9838 Description: Accessible Paved Parking and Public Entrance.



Laughlin Wildlife Field Office Site – FCA Site #9838 Description: Public Parking Pavement Sealing Needed.



Laughlin Wildlife Field Office Site – FCA Site #9838 Description: Rear Parking Lot Pavement and Shade Structure.



Shade Structure – FCA Building #4278 Description: View of the Structure.



Laughlin Wildlife Field Office – FCA Building #2470 Description: View of the Office Space.



Laughlin Wildlife Field Office – FCA Building #2470 Description: Arc Flash Labeling & Breaker Coordination Study Needed.



Laughlin Wildlife Field Office – FCA Building #2470 Description: Ceiling Repairs Needed.



Laughlin Wildlife Field Office – FCA Building #2470 Description: Vinyl Flooring Replacement Needed.